FIGURE P6-7

Problems 6-14 and 6-23. *From R. T. Hinkle, Problems in Kinematics, Prentice-Hall. Englewood Cliffs, NJ, 1954*

6-14   Find all the instant centers of the linkages shown in Figure P6-7.

†6-23   Generate and draw the fixed and moving centrodes of links 1 and 3 for the linkage in Figure P6-7a.