FIGURE P7-9

Problem 7-39

*†7-39   Figure P7-9 shows a linkage in one position. Find the instantaneous accelerations of points A, B, and P if link O_2A is rotating CW at 40 rad/sec.