



FIGURE P3-10

Problems 3-36 to 3-38

- *3-36 Find the Grashof condition, inversion, any limit positions, and the extreme values of the transmission angle (to graphical accuracy) of the linkage in Figure P3-10.
- 3-37 Draw the Roberts diagram and find the cognates of the linkage in Figure P3-10.
- 3-38 Find the three geared fivebar cognates of the linkage in Figure P3-10.

* Answers in Appendix F.