



FIGURE P3-11

Problems 3-39 to 3-41

- *3-39 Find the Grashof condition, any limit positions, and the extreme values of the transmission angle (to graphical accuracy) of the linkage in Figure P3-11.
- 3-40 Draw the Roberts diagram and find the cognates of the linkage in Figure P3-11.
- 3-41 Find the three geared fivebar cognates of the linkage in Figure P3-11.

* Answers in Appendix F.