

6-46 Figure P6-9 shows a linkage in one position. Find the instantaneous velocities of points A, B, and P if link O_2A is rotating CW at 40 rad/sec.