
ELECTRICAL INSULATION FOR ROTATING MACHINES

Design, Evaluation, Aging, Testing,
and Repair

Second Edition

GREG C. STONE

IAN CULBERT

EDWARD A. BOULTER

HUSSEIN DHIRANI

IEEE
PRESS
SERIES
ON POWER
ENGINEERING



 **IEEE**
IEEE PRESS

WILEY

CONTENTS

PREFACE

xix

CHAPTER 1 ROTATING MACHINE INSULATION SYSTEMS

1

- 1.1 Types of Rotating Machines 1
 - 1.1.1 AC Motors 2
 - 1.1.2 Synchronous Generators 4
 - 1.1.3 Induction Generators 6
 - 1.1.4 Permanent Magnet (PM) Synchronous Motors and Generators 7
 - 1.1.5 Classification by Cooling 7
- 1.2 Winding Components 9
 - 1.2.1 Stator Winding 9
 - 1.2.2 Insulated Rotor Windings 10
 - 1.2.3 Squirrel Cage Induction Motor Rotor Windings 11
- 1.3 Types of Stator Winding Construction 11
 - 1.3.1 Random-Wound Stators 12
 - 1.3.2 Form-Wound Stators—Coil Type 12
 - 1.3.3 Form-Wound Stators—Roebel Bar Type 13
- 1.4 Form-Wound Stator Winding Insulation System Features 14
 - 1.4.1 Strand Insulation 14
 - 1.4.2 Turn Insulation 17
 - 1.4.3 Groundwall Insulation 19
 - 1.4.4 Groundwall Partial Discharge Suppression 21
 - 1.4.5 Groundwall Stress Relief Coatings for Conventional Stators 24
 - 1.4.6 Surface Stress Relief Coatings for Inverter-Fed Stators 27
 - 1.4.7 Conductor Shields 29
 - 1.4.8 Mechanical Support in the Slot 30
 - 1.4.9 Mechanical Support in the End winding 32
 - 1.4.10 Transposition Insulation 34
- 1.5 Random-Wound Stator Winding Insulation System Features 36
 - 1.5.1 Partial Discharge Suppression in Inverter-Fed Random Windings 37
- 1.6 Rotor Winding Insulation System Components 38
 - 1.6.1 Salient Pole Rotor 40
 - 1.6.2 Round Rotors 41
 - 1.6.3 Induction Machine Wound Rotors 43
- References 45

CHAPTER 2 EVALUATING INSULATION MATERIALS AND SYSTEMS

47

- 2.1 Aging Stresses 49
 - 2.1.1 Thermal Stress 49

2.1.2	Electrical Stress	50
2.1.3	Ambient Stress (Factors)	52
2.1.4	Mechanical Stress	53
2.1.5	Radiation Stress	54
2.1.6	Multiple Stresses	54
2.2	Principles of Accelerated Aging Tests	54
2.2.1	Candidate and Reference Materials/Systems	55
2.2.2	Statistical Variation	55
2.2.3	Failure Indicators	61
2.3	Thermal Endurance Tests	62
2.3.1	Basic Principles	62
2.3.2	Thermal Identification and Classification	63
2.3.3	Insulating Material Thermal Aging Test Standards	64
2.3.4	Insulation System Thermal Aging Test Standards	64
2.3.5	Future Trends	67
2.4	Electrical Endurance Tests	67
2.4.1	Proprietary Tests for Form-Wound Coils	68
2.4.2	Standardized AC Voltage Endurance Test Methods for Form-Wound Coils/Bars	69
2.4.3	Voltage Endurance Tests for Inverter-Fed Windings	70
2.5	Thermal Cycling Tests	71
2.5.1	IEEE Thermal Cycling Test	72
2.5.2	IEC Thermal Cycling Test	73
2.6	Nuclear Environmental Qualification Tests	74
2.6.1	Environmental Qualification (EQ) by Testing	75
2.6.2	Environmental Qualification by Analysis	76
2.6.3	Environmental Qualification by a Combination of Testing and Analysis	77
2.7	Multifactor Stress Testing	77
2.8	Material Property Tests	78
	References	80

CHAPTER 3 *HISTORICAL DEVELOPMENT OF INSULATION MATERIALS AND SYSTEMS*

3.1	Natural Materials for Form-Wound Stator Coils	84
3.2	Early Synthetics for Form-Wound Stator Coils	86
3.3	Plastic Films and Non-Wovens	89
3.4	Liquid Synthetic Resins	90
3.4.1	Polyesters	90
3.4.2	Epoxides (Epoxy Resins)	92
3.5	Mica	95
3.5.1	Mica Splittings	95
3.5.2	Mica Paper	96
3.5.3	Mica Backing Materials	98
3.6	Glass Fibers	99
3.7	Laminates	100
3.8	Evolution of Wire and Strand Insulations	101
3.9	Manufacture of Random-Wound Stator Coils	102
3.10	Manufacture of Form-Wound Coils and Bars	103

3.10.1	Early Systems	103
3.10.2	Asphaltic Mica Systems	103
3.10.3	Individual Coil and Bar Thermoset Systems	104
3.10.4	Global VPI Systems	105
3.11	Wire Transposition Insulation	106
3.12	Methods of Taping Stator Groundwall Insulation	107
3.13	Insulating Liners, Separators, and Sleeving	109
3.13.1	Random-Wound Stators	109
3.13.2	Rotors	110
	References	110

CHAPTER 4 *STATOR WINDING INSULATION SYSTEMS IN CURRENT USE* **111**

4.1	Consolidation of Major Manufacturers	114
4.2	Description of Major Trademarked Form-Wound Stator Insulation Systems	115
4.2.1	Westinghouse Electric Co.: Thermalastic™	115
4.2.2	General Electric: Micapals I and II™, Epoxy Mica Mat™, Micapal HT™, and Hydromat™	116
4.2.3	Alstom, GEC Alstom, and Alstom Power: Isotenax™, Resitherm™, Resiflex™, Resivac™, and Duritenax™	117
4.2.4	Siemens AG, KWU: Micalastic™	118
4.2.5	Brown Boveri, ASEA, ABB, and Alstom Power: Micadur™, Micadur Compact™, Micapac™, and Micarex™	119
4.2.6	Toshiba Corporation: Tosrich™ and Tostight™	120
4.2.7	Mitsubishi Electric Corporation	121
4.2.8	Hitachi, Ltd.: Hi-Resin™, Hi-Mold™, and Super Hi-Resin™	121
4.2.9	Dongfang Electric Machinery	122
4.2.10	Harbin Electric Corporation (HEC)	122
4.2.11	Shanghai Electric Machinery	122
4.2.12	Jinan Power Equipment: Resitherm™, Micadur™, and Micadur Compact™	123
4.2.13	Summary of Present-Day Insulation Systems	123
4.3	Recent Developments for Form-Wound Insulation Systems	123
4.3.1	Reducing Groundwall Thermal Impedance	124
4.3.2	Increasing Electric Stress	125
4.3.3	Environmental Issues	126
4.4	Random-Wound Stator Insulation Systems	127
4.4.1	Magnet Wire Insulation	127
4.4.2	Phase and Ground Insulation	127
4.4.3	Varnish Treatment and Impregnation	128
	References	129

CHAPTER 5 *ROTOR WINDING INSULATION SYSTEMS* **133**

5.1	Rotor Slot and Turn Insulation	134
5.2	Collector Insulation	136
5.3	End Winding Insulation and Blocking	136
5.4	Retaining Ring Insulation	137
5.5	Direct-Cooled Rotor Insulation	138
5.6	Wound Rotors	139

5.7	Superconducting Synchronous Rotors	140
	References	141

CHAPTER 6 *ROTOR AND STATOR LAMINATED CORES*

143

6.1	Magnetic Materials	143
6.1.1	Magnetic Fields	143
6.1.2	Ferromagnetism	143
6.1.3	Magnetization Saturation Curve	144
6.1.4	Ferromagnetic Materials	144
6.1.5	Permeability	145
6.1.6	Hysteresis Loss	145
6.1.7	Eddy Current Loss	146
6.1.8	Other Factors Affecting Core Loss	146
6.1.9	Effect of Direction of the Grain	148
6.1.10	Effect of Temperature	148
6.1.11	Effect of Heat Treatment	148
6.1.12	Effect of Impurities and Alloying Elements	148
6.1.13	Silicon/Aluminum Steels	149
6.2	Mill-Applied Insulation	149
6.3	Lamination Punching and Laser Cutting	150
6.4	Annealing and Burr Removal	151
6.5	Enameling or Film Coatings	151
6.6	Stator and Rotor Core Construction	152
6.6.1	Stator Core Construction: General	152
6.6.2	Hydrogenerator and Large Motor Stator Core Assembly and Support	153
6.6.3	Turbogenerator Stator Core Assembly and Support	154
6.6.4	Smaller Motor and Generator Stator Cores	155
6.6.5	Rotor Core Construction	155
	References	157

CHAPTER 7 *GENERAL PRINCIPLES OF WINDING FAILURE, REPAIR AND REWINDING*

159

7.1	Failure Processes	159
7.1.1	Relative Failure Rates of Components	161
7.1.2	Factors Affecting Failure Mechanism Predominance	162
7.2	Factors Affecting Repair Decisions	164
7.3	Rapid Repair of Localized Stator Winding Damage	165
7.4	Cutting out Stator Coils After Failure	166
7.5	Bar/Coil Replacement and Half Coil Splice	167
7.6	Rewinding	168
	References	169

CHAPTER 8 *STATOR FAILURE MECHANISMS AND REPAIR*

171

8.1	Thermal Deterioration	171
8.1.1	General Process	171
8.1.2	Root Causes	174

8.1.3	Symptoms	175	
8.1.4	Remedies	176	
8.2	Thermal Cycling	176	
8.2.1	General Process	177	
8.2.2	Root Causes	180	
8.2.3	Symptoms	180	
8.2.4	Remedies	181	
8.3	Inadequate Resin Impregnation or Dipping	181	
8.3.1	General Process	182	
8.3.2	Root Causes	183	
8.3.3	Symptoms	184	
8.3.4	Remedies	184	
8.4	Loose Coils in the Slot	185	
8.4.1	General Process	185	
8.4.2	Root Causes	186	
8.4.3	Symptoms	189	
8.4.4	Remedies	190	
8.5	Semiconductive Coating Failure	190	
8.5.1	General Process	190	
8.5.2	Root Causes	191	
8.5.3	Symptoms	192	
8.5.4	Remedies	193	
8.6	Semiconductive/Grading Coating Overlap Failure	194	
8.6.1	General Process	194	
8.6.2	Root Causes	195	
8.6.3	Symptoms	196	
8.6.4	Remedies	196	
8.7	High Intensity Slot Discharge	197	
8.7.1	General Process	198	
8.7.2	Root Causes	198	
8.7.3	Symptoms	199	
8.7.4	Repairs	199	
8.8	Vibration Sparking (Spark Erosion)	199	
8.8.1	General Process	199	
8.8.2	Root Cause	201	
8.8.3	Symptoms	201	
8.8.4	Repair	202	
8.9	Transient Voltage Surges	202	
8.9.1	General Process	203	
8.9.2	Root Causes	204	
8.9.3	Symptoms	204	
8.9.4	Remedies	206	
8.10	Repetitive Voltage Surges Due to Drives	207	
8.10.1	General Process	207	
8.10.2	Root Cause	209	
8.10.3	Symptoms	209	
8.10.4	Remedies	210	
8.11	Contamination (Electrical Tracking)	211	
8.11.1	General Process	211	
8.11.2	Root Causes	214	

X CONTENTS

8.11.3	Symptoms	214
8.11.4	Remedies	214
8.12	Abrasive Particles	216
8.12.1	General Process	216
8.12.2	Root Causes	216
8.12.3	Symptoms and Remedies	216
8.13	Chemical Attack	217
8.13.1	General Process	217
8.13.2	Root Causes	218
8.13.3	Symptoms	218
8.13.4	Remedies	219
8.14	Inadequate End Winding Spacing	219
8.14.1	General Process	220
8.14.2	Root Causes	222
8.14.3	Symptoms	222
8.14.4	Remedies	222
8.15	End Winding Vibration	224
8.15.1	General Process	224
8.15.2	Root Causes	225
8.15.3	Symptoms	226
8.15.4	Remedies	227
8.16	Stator Coolant Water Leaks	228
8.16.1	General Process	228
8.16.2	Root Causes	229
8.16.3	Symptoms	230
8.16.4	Remedies	230
8.17	Poor Electrical Connections	231
8.17.1	General Process	231
8.17.2	Root Causes	232
8.17.3	Symptoms	232
8.17.4	Remedies	233
	References	233

CHAPTER 9 *ROUND ROTOR WINDING FAILURE MECHANISMS AND REPAIR*

235

9.1	Thermal Deterioration	235
9.1.1	General Process	236
9.1.2	Root Cause	236
9.1.3	Symptoms	237
9.2	Thermal Cycling	237
9.2.1	General Process	238
9.2.2	Root Cause	238
9.2.3	Symptoms	240
9.3	Abrasion Due to Imbalance or Turning Gear Operation (Copper Dusting)	241
9.3.1	General Process	242
9.3.2	Root Causes	243
9.3.3	Symptoms	244
9.4	Pollution (Tracking)	244
9.4.1	General Process	244
9.4.2	Root Causes	245

9.4.3	Common Symptoms	245
9.5	Repetitive Voltage Surges	245
9.5.1	General Process	246
9.5.2	Root Causes	246
9.5.3	Common Symptoms	247
9.6	Centrifugal Force	247
9.6.1	General Process	247
9.6.2	Root Causes	247
9.6.3	Common Symptoms	248
9.7	Operating Without Field Current	249
9.7.1	Loss of Field During Operation	249
9.7.2	Inadvertent Closure of Generator Breaker	249
9.7.3	Root Causes	250
9.7.4	Common Symptoms	250
9.8	Remedies	250
	References	252

CHAPTER 10 *SALIENT POLE ROTOR WINDING FAILURE MECHANISMS
AND REPAIR*

253

10.1	Thermal Deterioration	253
10.1.1	General Process	253
10.1.2	Root Causes	254
10.1.3	Common Symptoms	254
10.2	Thermal Cycling	255
10.2.1	General Process	255
10.2.2	Root Causes	255
10.2.3	Common Symptoms	256
10.3	Pollution (Tracking and Moisture Absorption)	256
10.3.1	General Process	257
10.3.2	Root Causes	257
10.3.3	Common Symptoms	258
10.4	Abrasive Particles	258
10.4.1	General Process	258
10.4.2	Root Causes	258
10.4.3	Common Symptom	259
10.5	Centrifugal Force	259
10.5.1	General Process	259
10.5.2	Root Causes	259
10.5.3	Common Symptoms	259
10.6	Repetitive Voltage Surges	260
10.6.1	General Process	260
10.6.2	Root Causes	260
10.6.3	Common Symptoms	261
10.7	Salient Pole Repair	261
	References	263

CHAPTER 11 *WOUND ROTOR WINDING FAILURE MECHANISMS AND REPAIR*

265

11.1	Voltage Surges	266
------	----------------	-----

11.1.1	General Process	266
11.1.2	Root Causes	267
11.1.3	Common Symptoms	267
11.2	Unbalanced Stator Voltages	267
11.2.1	General Process	267
11.2.2	Root Causes	268
11.2.3	Common Symptoms	268
11.3	High Resistance Connections-Bar Lap and Wave Windings	268
11.3.1	General Process	268
11.3.2	Root Causes	268
11.3.3	Common Symptoms	268
11.4	End Winding Banding Failures	269
11.4.1	General Process	269
11.4.2	Root Causes	269
11.4.3	Common Symptoms	269
11.5	Slip Ring Insulation Shorting and Grounding	270
11.5.1	General Process	270
11.5.2	Root Causes	270
11.6	Wound Rotor Winding Repair	271
11.6.1	Failed Windings	271
11.6.2	Contaminated Windings and Slip Ring Insulation	271
11.6.3	Failed Connections in Bar-Type Windings	271
11.6.4	Damaged End Winding Banding	271
11.6.5	Failed or Contaminated Slip Ring Insulation	272
	References	272

CHAPTER 12 *SQUIRREL CAGE INDUCTION ROTOR WINDING FAILURE MECHANISMS AND REPAIR*

273

12.1	Thermal	273
12.1.1	General Process	274
12.1.2	Root Causes	274
12.1.3	Common Symptoms	275
12.2	Cyclic Mechanical Stressing	275
12.2.1	General Process	276
12.2.2	Root Causes	277
12.2.3	Common Symptoms	278
12.3	Poor Design/Manufacture	278
12.3.1	General Process and Root Causes	279
12.3.2	Common Symptoms	281
12.4	Repairs	283
	References	284

CHAPTER 13 *CORE LAMINATION INSULATION FAILURE AND REPAIR*

285

13.1	Thermal Deterioration	285
13.1.1	General Process	286
13.1.2	Root Causes	286
13.1.3	Common Symptoms	289
13.2	Electrical Degradation	290

13.2.1	General Process	290
13.2.2	Root Causes	291
13.2.3	Common Symptoms	294
13.3	Mechanical Degradation	295
13.3.1	General Process	295
13.3.2	Root Causes	296
13.3.3	Symptoms	301
13.4	Failures Due to Manufacturing Defects	303
13.4.1	General Process	303
13.4.2	Root Causes	304
13.4.3	Symptoms	304
13.5	Core Repairs	305
13.5.1	Loose Cores	305
13.5.2	Core Insulation Shorting	306
13.5.3	Core Damage Due to Winding Electrical Faults	307
13.5.4	False Tooth	308
13.5.5	Cracked Through-Bolt Insulation	308
13.5.6	Split Core Repairs	308
	References	309

CHAPTER 14 *GENERAL PRINCIPLES OF TESTING AND MONITORING*
311

14.1	Purpose of Testing and Monitoring	311
14.1.1	Assessing Winding Condition and Remaining Winding Life	311
14.1.2	Prioritizing Maintenance	312
14.1.3	Commissioning and Warranty Testing	312
14.1.4	Determining Root Cause of Failure	313
14.2	Off-Line Testing Versus On-Line Monitoring	313
14.3	Role of Visual Inspections	314
14.4	Expert Systems to Convert Data Into Information	315
	References	316

CHAPTER 15 *OFF-LINE ROTOR AND STATOR WINDING TESTS*
317

15.1	Insulation Resistance and Polarization Index	317
15.1.1	Purpose and Theory	320
15.1.2	Test Method	322
15.1.3	Interpretation	324
15.2	DC Hipot Test	326
15.2.1	Purpose and Theory	326
15.2.2	Test Method	327
15.2.3	Interpretation	329
15.3	Polarization/Depolarization Current (PDC)	330
15.3.1	Purpose and Theory	330
15.3.2	Test Method	331
15.3.3	Interpretation	331
15.4	DC Conductivity	331
15.4.1	Purpose and Theory	332
15.4.2	Test Method	333
15.4.3	Interpretation	333

15.5	Poor Connection Hot Spot (High Current-Infrared Camera)	334
15.5.1	Purpose and Theory	334
15.5.2	Test Method	335
15.5.3	Interpretation	335
15.6	AC Hipot	335
15.6.1	Purpose and Theory	336
15.6.2	Test Method	337
15.6.3	Interpretation	338
15.7	Capacitance	339
15.7.1	Purpose and Theory	339
15.7.2	Test Method	340
15.7.3	Interpretation	341
15.8	Stator Capacitance Tip-Up	342
15.8.1	Purpose and Theory	342
15.8.2	Test Method	342
15.8.3	Interpretation	343
15.9	Capacitive Impedance Test for Motor Stators	344
15.10	Dissipation (or Power) Factor	344
15.10.1	Purpose and Theory	345
15.10.2	Test Method	345
15.10.3	Interpretation	347
15.11	Power (Dissipation) Factor Tip-Up	348
15.11.1	Purpose and Theory	348
15.11.2	Test Method	349
15.11.3	Interpretation	350
15.12	Off-Line Partial Discharge for Conventional Windings	350
15.12.1	Purpose and Theory	351
15.12.2	Test Method	352
15.12.3	Interpretation	354
15.13	Off-Line Partial Discharge for Inverter-Fed Windings	357
15.13.1	Purpose and Theory	357
15.13.2	Test Method and Interpretation	358
15.14	Stator Blackout and Ultraviolet Imaging	359
15.14.1	Purpose and Theory	359
15.14.2	Test Method	360
15.14.3	Interpretation	360
15.15	Stator Partial Discharge Probe	361
15.15.1	Purpose and Theory	361
15.15.2	Test Method	362
15.15.3	Interpretation	362
15.16	Stator Surge Voltage	363
15.16.1	Purpose and Theory	363
15.16.2	Test Method	365
15.16.3	Interpretation	366
15.17	Inductive Impedance	367
15.18	Semiconductive Coating Contact Resistance	368
15.18.1	Purpose and Theory	368
15.18.2	Test Method	369
15.18.3	Interpretation	369
15.19	Conductor Coolant Tube Resistance	369

15.19.1	Purpose and Test Method	369
15.20	Stator Wedge Tap	370
15.20.1	Purpose and Theory	370
15.20.2	Test Method	370
15.20.3	Interpretation	372
15.21	Slot Side Clearance	373
15.21.1	Purpose and Theory	373
15.21.2	Test Method	373
15.21.3	Interpretation	373
15.22	Stator Slot Radial Clearance	374
15.22.1	Purpose and Theory	374
15.22.2	Test Method	374
15.22.3	Interpretation	374
15.23	Stator End Winding Bump	375
15.23.1	Purpose and Theory	375
15.23.2	Test Method	375
15.23.3	Interpretation	376
15.24	Stator Pressure and Vacuum Decay	377
15.24.1	Purpose and Theory	377
15.24.2	Test Methods and Interpretation	377
15.25	Rotor Pole Drop (Voltage Drop)	378
15.25.1	Purpose and Theory	379
15.25.2	Test Method—Salient Pole Rotor	379
15.25.3	Test Method—Round Rotors	380
15.25.4	Interpretation	380
15.26	Rotor RSO and Surge	380
15.26.1	Purpose and Theory	380
15.26.2	Test Method	381
15.26.3	Interpretation	382
15.27	Rotor Growler	382
15.27.1	Purpose and Theory	383
15.27.2	Test Method	383
15.27.3	Interpretation	383
15.28	Rotor Fluorescent Dye Penetrant	383
15.28.1	Purpose and Theory	383
15.28.2	Test Method and Interpretation	384
15.29	Rotor Rated Flux	384
15.29.1	Purpose and Theory	384
15.29.2	Test Method	384
15.29.3	Interpretation	384
15.30	Rotor Single-Phase Rotation	385
15.30.1	Purpose and Theory	385
15.30.2	Test Method	385
15.30.3	Interpretation	385
	References	385

CHAPTER 16 *IN-SERVICE MONITORING OF STATOR AND ROTOR WINDINGS*

389

16.1	Thermal Monitoring	390
16.1.1	Stator Winding Point Sensors	390

16.1.2	Rotor Winding Sensors	392
16.1.3	Data Acquisition and Interpretation	393
16.1.4	Thermography	394
16.2	Condition Monitors and Tagging Compounds	395
16.2.1	Monitoring Principles	395
16.2.2	Interpretation	397
16.3	Ozone	398
16.3.1	Monitoring Principles	398
16.3.2	Interpretation	399
16.4	Online Partial Discharge Monitor	400
16.4.1	Monitoring Principles	400
16.4.2	Interpretation	408
16.5	Online Capacitance and Dissipation Factor	415
16.5.1	Monitoring Principle	415
16.5.2	Data Acquisition and Interpretation	416
16.6	Endwinding Vibration Monitor	417
16.6.1	Monitoring Principles	417
16.6.2	Data Acquisition and Interpretation	418
16.7	Synchronous Rotor Flux Monitor	420
16.7.1	Monitoring Principles	421
16.7.2	Data Acquisition and Interpretation	425
16.8	Current Signature Analysis	427
16.8.1	Monitoring Principles	427
16.8.2	Data Acquisition	429
16.8.3	Interpretation	430
16.9	Bearing Vibration Monitor	432
16.9.1	Vibration Sensors	432
16.9.2	Induction Motor Monitoring	433
16.9.3	Synchronous Machine Monitoring	434
16.10	Stator Winding Water Leak Monitoring	435
	References	435

CHAPTER 17 *CORE TESTING*

17.1	Knife	439
17.1.1	Purpose and Theory	439
17.1.2	Test Method	440
17.1.3	Interpretation	440
17.2	Rated Flux	441
17.2.1	Purpose and Theory	441
17.2.2	Test Method	443
17.2.3	Interpretation	449
17.3	Core Loss	450
17.3.1	Purpose and Theory	450
17.3.2	Test Method	450
17.3.3	Interpretation	450
17.4	Low Core Flux (EI-CID)	451
17.4.1	Purpose and Theory	452
17.4.2	Test Method	453

17.4.3	Interpretation	457
	References	461

CHAPTER 18 *NEW MACHINE WINDING AND REWIND SPECIFICATIONS* **463**

18.1	Objective of Stator and Rotor Winding Specifications	464
18.2	Trade-Offs Between Detailed and General Specifications	464
18.3	General Items for Specifications	465
18.4	Technical Requirements for New Stator Windings	467
18.5	Technical Requirements for Insulated Rotor Windings	475
18.5.1	New Round Rotor Windings	475
18.5.2	Refurbishment and Replacement of Existing Round Rotor Windings	478
18.5.3	New Salient Pole Windings	481
18.5.4	Refurbishment and Repair of Existing Salient Pole Windings	484
	References	486

CHAPTER 19 *ACCEPTANCE AND SITE TESTING OF NEW WINDINGS* **487**

19.1	Stator Winding Insulation System Prequalification Tests	487
19.1.1	Dissipation Factor Tip-Up	488
19.1.2	Partial Discharge Test for Conventional Windings	488
19.1.3	Partial Discharge Test for Inverter Fed Windings	489
19.1.4	Impulse (Surge)	490
19.1.5	Voltage Endurance for Conventional Windings	490
19.1.6	Voltage Endurance for Form-Wound Inverter Fed Windings	492
19.1.7	Thermal Cycling	492
19.1.8	Thermal Classification	493
19.2	Stator Winding Insulation System Factory and On-Site Tests	494
19.2.1	Insulation Resistance and Polarization Index	494
19.2.2	Phase Resistance and/or Thermal Imaging	495
19.2.3	AC and DC Hipot	495
19.2.4	Impulse (Surge)	497
19.2.5	Strand-to-Strand	498
19.2.6	Power Factor Tip-Up	498
19.2.7	Partial Discharge	498
19.2.8	Semiconductive Coating Test	499
19.2.9	Wedge Tap	499
19.2.10	Endwinding Bump	500
19.3	Factory and On-Site Tests for Rotor Windings	501
19.3.1	Tests Applicable to All Insulated Windings	501
19.3.2	Round Rotor Synchronous Machine Windings	502
19.3.3	Salient Pole Synchronous Machine Windings	503
19.3.4	Wound Induction Rotor Windings	504
19.3.5	Squirrel Cage Rotor Windings	504
19.4	Core Insulation Factory and On-Site Tests	505
19.4.1	Core Tightness	505
19.4.2	Rated Flux	505
19.4.3	Low Flux (EI-CID)	506
	References	506

CHAPTER 20	<i>MAINTENANCE STRATEGIES</i>	509
20.1	Maintenance and Inspection Options	509
20.1.1	Breakdown or Corrective Maintenance	510
20.1.2	Time-Based or Preventative Maintenance	510
20.1.3	Condition-Based or Predictive Maintenance	512
20.1.4	Inspections	513
20.2	Maintenance Strategies for Various Machine Types and Applications	515
20.2.1	Turbogenerators	516
20.2.2	Salient Pole Generators and Motors	519
20.2.3	Squirrel Cage and Wound-Rotor Induction Motors	521
	Reference	525
APPENDIX A	<i>INSULATION MATERIAL TABLES</i>	527
APPENDIX B	<i>INSULATION SYSTEM TABLES</i>	553
INDEX		629
